

## GD32 Virtual ComPort User Guide

- Step 1 Connect the detector to PC with the provided download cable, turn on the machine.
- Step 2 Right-click *My Computer* and select *Manage* from the context menu.





